Oil Field Environmental Incident Summary

Responsible Party: MARATHON OIL COMPANY **Well Operator:** MARATHON OIL COMPANY

Well Name: APPLEDOORN SWD 1

Field Name: BAILEY Well File #: 90126

Date Incident:6/20/2017Time Incident:12:00Facility ID Number:County:DUNNTwp:145Rng:93Sec:19Qtr:

Location Description:

Submitted By: Garrett Lunde Received By:

Contact Person: Garrett Lunde

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 120 Barrels 120 Barrels

Other

Description of Other Released Contaminant:

Produced/Brine Water

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None. Release was contained inside lined containment.

Areal Extent:

N/A

Potential Environmental Impacts:

None. Release was contained inside lined containment.

Action Taken or Planned:

Vacuum truck removed all standing fluids and affected solids (on top of lined containment) which will be taken to an authorized disposal site.

Investigation is ongoing to determine cause of release and identify potential corrective actions.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 6/21/2017 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained on location within containment. NDIC retains oversight.

Page 2 of 2